

15448-0506

1/16




Fig. 1




Fig. 2

15448-0506

2/16







Fig. 3

15448-0506

3/16



*Fig. 4*




*Fig. 5*

FIG. 5


15448-0506

4/16



Charge Storage Delay Stuck @ 1

*Fig. 6*



*Fig. 7*

15448-0506

5/16




Fig. 8





Fig. 9

FOR PUBLICATION



*Fig. 10*

15448-0506

+

7/16




Fig. 11





Fig. 12

+

15448-0506

8/13



*Fig. 13*



15448-0506

9/16




Fig. 14

15448-0506

10/16




Fig. 15

+

*Fig. 16*



+




Fig. 18




Fig. 19




Fig. 20

15448-0506

15/16




Fig. 21




Fig. 22